TECHNICAL DATA SHEET

SEASHIELDTM FX-523 EPOXY ADHESIVE

SeaShield FX-523 Epoxy Adhesive is a two-component, 100% solids, thixotropic, Description flexible, non-sag adhesive formulated to bond spacers/stand-offs to fiberglass jackets and other construction materials. · To bond spacer/stand-offs to the SeaShield Fiberglass jackets Uses To bond common construction materials To bond dissimilar materials Excellent adhesion to fiberglass **Features** · Bonds well to most construction materials · Thixotropic gel with no sag · Suitable for saltwater marine applications Easily applied with trowel or putty knife Excellent abrasion resistance All surfaces must be sound, clean and free of all contaminants that could impair **Surface Prep** product adhesion or performance. Remove all oils, greases, dirt and wax solutions from surface. Surface must be at least 40°F (4°C) prior to application. A. Steel Surfaces: The recommended method is to prepare the surface by abrasive blasting per SSPC-SP6/NACE 3 Commercial Blast with a 2-3 mil surface profile. Scraping and other manual means of surface preparation should be avoided since they tend to polish the surface. B. Concrete: Concrete should be a minimum of 28 days old and fully cured prior to application. Prepare the surface by abrasive blasting per SSPC-SP13/ NACE 6, ICRI Guideline 310.2R CSP3.5. C. Masonry: Prepare surface by abrasive blasting or other means to achieve a clean and sound surface. D. Fiberglass Jackets : Fiberglass surface must be sound, clean and free of all contaminants that could impair product adhesion or performance. Roughen fiberglass by sanding on areas where spacer/stand-offs are to be adhered.

TECHN	ICA	L D	A T	A S	5 H I	E E T	
Mixing	For best mixing & application, components shall be at a min. 70°F (21°C) prior to use. Do not prepare more material than can be used within the pot life of the product. Do not add thinner. Proportion components at a 1 Part A:1 Part B ratio by volume in a small container or flat cardboard. Mix components together thoroughly with a mixing stick for 2-3 minutes until a consistent color is achieved.						
Application	Apply mixed SeaShield FX-523 Epoxy to the prepared surface or spacer/stand-off with a putty knife. Place materials together and secure them to prevent movement until fully cured. Immediately remove any excess material by solvent wiping with cotton clothes before the product cures.						
Storage	Store in a dry, well-ventilated area between 40°F and 95°F (4°C and 35°C) in original, unopened containers. Shelf life is at least 24 months under these conditions. It is recommended that all components be stored between 68°F and 86°C (20°C and 30°C) for 24 hours prior to use for optimum pumping and productivity.						
Cleaning	Clean tools, spills and drips from surfaces with Simple Green, MEK, acetone etc. Cured material can only be removed by mechanical means.						
HSE	Wear protective clo and eyes. See the	thing and ensur safety data shee	e adequate et (SDS) for	ventilation. A further inform	void contac ation.	t with skin	
Packaging	Kit Size	Part	A		Part B		
	2 qt. (1.9 L) 1 qt. (0.95 L) 1 qt. (0.95 L) Note - Packaged 4 kits per case.						

TECHNICAL DATA SHEET

Tech Data

Properties	Imperial	Metric		
Solids Content	100%	100%		
Base Component – (Unmixed) @ 77°F (25°C)				
Viscosity	1,000,000 cps	1,000,000 cps		
Color	Opaque/Clear	Opaque/Clear		
Hardener – (Unmixed) @ 77°F (25°C)				
Viscosity	1,000,000 cps	1,000,000 cps		
Color	Beige	Beige		
Mixed Material @ 77°F (25°C)				
Viscosity	850,000 cps	850,000 cps		
Color	Beige	Beige		
Mixing Ratio (A/B) by Volume	1 parts Base:1 part Hardener	1 parts Base:1 part Hardener		
Consistency (ASTM C881)	Non-sag	Non-sag		
Gel Time	15 to 18 minutes	15 to 18 minutes		
Tensile Strength (ASTM D63 @ 7days)	700 psi	4.8 MPa		
Tensile Elongation (ASTM D63 @ 7days)	30%	30%		
Pull-Off Adhesion (RT)	2587 psi	17.8 MPa		
Product Yield	231 cubic in./US gal	0.001 cubic dm/L		
Application Temperature	40°F to 125°F	5°C to 52°C		
Service Temperature	-40°F to 150°F	-40°C to 65°C		



DENSO, INC.

HOUSTON: 9710 Telge Road, Houston, Texas, U.S.A. 77095 Tel: 281-821-3355 Fax: 281-821-0304 TORONTO: 90 Ironside Crescent, Unit 12, Toronto, Ontario, Canada M1X1M3 Tel: 416-291-3435 Fax: 416-291-0898

www.densona.com

info@densona.com

A Member of Winn & Coales International

The information given on this sheet is intended as a general guide only and should not be used for specification purposes. We believe the information to be accurate and reliable but do not guarantee it. We assume no responsibility for the use of this information. Users must, by their own tests, determine the suitability of the products and information supplied by us for their own particular purposes. No patent liability can be assumed.